



Shower Mixing Valve Case Study

Customer: Double Tree By Hilton, Port Huron, MI

Category: Commercial

Application: Scale prevention for a medium sized hotel



The Challenge: Though staff initially stated “We don’t have any issues with scale” this proved not to be the case. Contractors refurbishing the hotel were accommodated in 4 rooms and had been working at the property for just 4 weeks when newly installed shower fixtures started to malfunction. The Leonard mixing valve (shown above and to the left) was removed and large scale deposits were found.

The Solution: A Scaletron unit will be installed in the near future.

Results: To be posted.